

GÜNCEL TÜRKÇE OBD II ARIZA KODLARI
TEKNİK BİLGİLER
ARIZA TESPİT ÇHAZLARI

LAND ROVER

P1137	Land Rover	HO2S Failed To Switch To Rich, Bank "A"
P1138	Land Rover	HO2S Failed To Switch To Lean, Bank "A"
P1157	Land Rover	HO2S Failed To Switch To Rich, Bank "B"
P1158	Land Rover	HO2S Failed To Switch To Lean, Bank "B"
P1171	Land Rover	System Too lean, Bank A & Bank B
P1172	Land Rover	System Too Rich, Bank A & Bank B
P1176	Land Rover	FMFR Correction At Maximum Positive Value
P1177	Land Rover	FMFR Correction At maximum Negative Value
P1178	Land Rover	AMFR Correction At Maximum Positive Value
P1179	Land Rover	AMFR Correction At Maximum Negative Value
P1185	Land Rover	HO2S Heater Circuit Open, Upstream Sensors
P1186	Land Rover	HO2S Heater Short Circuit, Upstream Sensors
P1187	Land Rover	HO2S Heater Short Circuit, Upstream Sensors
P1188	Land Rover	HO2S Heater Circuit High Resistance, Upstream Sensors
P1189	Land Rover	HO2S heater Circuit Type 1 Low Resistance, Upstream
P1190	Land Rover	HO2S heater Circuit Type 2 Low Resistance, Upstream
P1191	Land Rover	HO2S Heater Circuit Open, Downstream Sensors
P1192	Land Rover	HO2S Heater Short Circuit, Downstream Sensors
P1193	Land Rover	HO2S Heater Circuit Inferred Open Circuit, Downstream Sensors
P1194	Land Rover	HO2S Heater Circuit High Resistance, Downstream Sensors
P1195	Land Rover	HO2S Heater Circuit Type 1 Low Resistance, Downstream
P1196	Land Rover	HO2S heater Circuit Type 2 Low Resistance, Downstream
P1199	Land Rover	Fuel Level Sensor Circuit Fault
P1201	Land Rover	Injector Open Circuit Or Ground Short, Cylinder 1
P1202	Land Rover	Injector Open Circuit Or Ground Short, Cylinder 2
P1208	Land Rover	Injector Open Circuit Or Ground Short, Cyl. 8
P1230	Land Rover	Fuel Pump Relay Open
P1231	Land Rover	Fuel Pump Relay Short Circuit To Battery Supply
P1232	Land Rover	Fuel Pump Relay Short Circuit To Ground
P1313	Land Rover	Misfire Likely To Damage Catalyst, Bank A
P1314	Land Rover	Misfire Likely To Damage Catalyst, Bank B
P1315	Land Rover	Persistent Misfire
P1316	Land Rover	Misfire Causing Excessive Emissions
P1317	Land Rover	ABS Rough Road Line Low Fault Detected
P1318	Land Rover	ABS Rough Road Line High Fault Detected
P1361	Land Rover	No Ignition Coil Activation, Coil 1
P1362	Land Rover	No Ignition Coil Activation, Coil 2
P1363	Land Rover	No Ignition Coil Activation, Coil 3
P1364	Land Rover	No Ignition Coil Activation, Coil 4
P1371	Land Rover	Early Ignition Coil Activation, Coil 1
P1372	Land Rover	Early Ignition Coil Activation, Coil 2
P1373	Land Rover	Early Ignition Coil Activation, Coil 3
P1374	Land Rover	Early Ignition Coil Activation, Coil 4
P1440	Land Rover	EVAP Purge Valve Stuck Open

P1447 Land Rover Purge Canister Closure Valve Poor Performance
P1496 Land Rover EVAP system gross leak detected
P1508 Land Rover IAC Motor Circuit Open
P1509 Land Rover IAC Motor Circuit Short
P1514 Land Rover Neutral Drive Load Fault L
P1516 Land Rover Neutral Drive Gear Change Fault
P1517 Land Rover Neutral Drive Cranking Fault
P1550 Land Rover IACV Circuit
P1607 Land Rover MIL Circuit Short
P1621 Land Rover Communications With Security ECM Not Within Expected Time
P1622 Land Rover More Than One Wrong Security Code Received By ECM
P1701 Land Rover Transfer Box Line Fault
P1703 Land Rover Transfer Box Line Open Circuit Short Fault
P1708 Land Rover Transfer Bow Line Short Circuit Fault
P1775 Land Rover Gearbox Fault
P1776 Land Rover Gearbox Ignition Retard Request Duration Fault
P1777 Land Rover Gearbox Ignition Retard Request Line Fault

www.dogacelektronik.com

GÜNCEL TÜRKÇE OBD II ARIZA KODLARI
TEKNİK BİLGİLER
ARIZA TESPİT CİHAZLARI